

FIRE TECHNOLOGY SERVICES

Confidential Report

Our Ref: 27/03523E/05/15

Notified Body for PPE Directive, Construction Products Regulation & Marine Equipment Directive I.D. No. 0338 & 0339 British Carpet Technical Centre Wira House, West Park Ring Road, Leeds, LS16 6QL



Tel No: +44 (0)113 2591999



19 May 2015

BTTG Testing & Certification Ltd. Wira House West Park Ring Road Leeds, LS16 6QL England

> Tel: +44 (0)113 259 1999 Web:http://www.bttg.co.uk Email:CSLeeds@bttg.co.uk

Our Ref: 27/03523E/05/15 Your Ref:		Page 1 of 5
Client:	Muraspec Tonbridge Road East Peckham Tonbridge Kent TN12 5JX	
Job Title:	Fire Test on One Sample of Fabric	
Clients Order Ref:		
Date of Receipt:	5 May 2015	
Description of Sample:	One sample of fabric, referenced: Colourways .	
Work Requested:	Fire Technology Services were requested to carry out the sample supplied to BS EN 1021 Parts 1 & 2.	t a fire test on





> Tel: +44 (0)113 259 1999 Web:http://www.bttg.co.uk Email:CSLeeds@bttg.co.uk

19 May 2015

Page 2 of 5

Our Ref: 27/03523E/05/15 Your Ref:

Muraspec

FIRE TESTS ACCORDING TO BS EN 1021-1 2006 Assessment of the ignitability of upholstered furniture. Part I. Ignition Source : Smouldering cigarette

Date of Test: 14/05/15

Conditioning

The sample was water-soaked in accordance with this standard and Immediately prior to testing the sample was conditioned for at least 16 hours at a temperature of $23\pm2^{\circ}$ C and relative humidity of $50\pm5\%$.

The sample was tested in a room of volume 25m³ and 23°C.

Procedure

The test was carried out in accordance with BS EN 1021-1. The sponsor sampled the material and the specimens were cut from the sample received to the dimensions set out in the standard.

The specimens were mounted over fillings of standard non-FR polyurethane foam of density about 22Kg/m³.

Tests were made using ignition source 0 in accordance with paragraph 9 of the above standard.

Requirements

The specimens shall not:-

- a) display escalating combustion requiring active extinction.
- b) smoulder or burn until it is essentially consumed within the test duration.
- c) smoulder or burn to the extremities of the specimen, or through the full thickness, within the duration of the test.
- d) smoulder for more than one hour.
- e) show evidence of charring, other than discolouration, for more than 100mm in any direction apart from the nearest part of the original position of the source.





> Tel: +44 (0)113 259 1999 Web:http://www.bttg.co.uk Email:CSLeeds@bttg.co.uk

> > Page 3 of 5

19 May 2015

Our Ref: 27/03523E/05/15 Your Ref:

Muraspec

Results

	Cigarette		0	
	1	2	Comments	
Smouldering Criteria (Yes/No)				
Unsafe escalating combustion	No	No		
Test assembly consumed	No	No		
Smoulders to extremities	No	No		
Smoulders through thickness	No	No		
Smoulders more than1 hour	No	No		
More than 100mm from source	No	No		
Ignitability Performance (Yes/No)				
Unsafe escalating combustion	No	No		
Test assembly consumed	No	No		
Flames to extremities	No	No		
Flames through thickness	No	No		
Ignition / Non Ignition (I/NI)	NI	NI		

The test results relate only to the ignitability of the combination of materials under the particular conditions of test; they are not intended as a means of assessing the full potential fire hazard of the materials in use.

Comments

A NI designation indicates that the sample met the performance requirements.





> Tel: +44 (0)113 259 1999 Web:http://www.bttg.co.uk Email:CSLeeds@bttg.co.uk

19 May 2015

Page 4 of 5

Our Ref: 27/03523E/05/15 Your Ref:

Muraspec

FIRE TESTS ACCORDING TO BS EN 1021-2 2006 Assessment of the ignitability of upholstered furniture. Part 2. Ignition Source : Match flame equivalent.

Date of Test: 14/05/15

Conditioning

The sample was water-soaked in accordance with this standard and Immediately prior to testing the sample was conditioned for at least 16 hours at a temperature of $23\pm2^{\circ}$ C and relative humidity of $50\pm5\%$.

The sample was tested in a room of volume 25m³ and 23°C.

Procedure

The test was carried out in accordance with BS EN 1021-2. The sponsor sampled the material and the specimens were cut from the sample received to the dimensions set out in the standard.

The specimens were mounted over fillings of standard non-FR polyurethane foam of density about 22Kg/m³.

Tests were made using ignition source 1 in accordance with paragraph 9 of the above standard.

Requirements

The specimens shall not:-

- a) display escalating combustion requiring active extinction.
- b) smoulder or burn until it is essentially consumed within the test duration.
- c) smoulder or burn to the extremities of the specimen, or through the full thickness, within the duration of the test.
- d) smoulder for more than one hour.
- e) show evidence of charring, other than discolouration, for more than 100mm in any direction apart from the nearest part of the original position of the source.
- f) burn for more than 120s after removal of the burner tube.





> Tel: +44 (0)113 259 1999 Web:http://www.bttg.co.uk Email:CSLeeds@bttg.co.uk

> > Page 5 of 5

19 May 2015

Our Ref: 27/03523E/05/15 Your Ref:

Muraspec

Results

	Match Flame Equivalent		Comments
	1	2	
Smouldering Criteria (Yes/No)		·	
Unsafe escalating combustion	No	No	
Test assembly consumed	No	No	
Smoulders to extremities	No	No	
Smoulders through thickness	No	No	
Smoulders more than 1 hour	No	No	
More than 100mm from source	No	No	
Ignitability Performance (Yes/No)			
Unsafe escalating combustion	No	No	
Test assembly consumed	No	No	
Flames to extremities	No	No	
Flames through thickness	No	No	
Flames longer than120 seconds	No	No	
Ignition / Non Ignition (I/NI)	NI	NI	

The test results relate only to the ignitability of the combination of materials under the particular conditions of test; they are not intended as a means of assessing the full potential fire hazard of the materials in use.

Comments

A NI designation indicates that the sample met the performance requirements.

An estimation of uncertainty of measurement has not been taken into account when making a judgement to any pass/fail criteria.

..... P Doherty, Operational Head Reported by:....

Enquiries concerning this report should be addressed to Customer Services.

